

MULTI -VOLTAGE WIRING DIAGRAM

Key:

L = AC LIVE

N = AC LIVE

- = DC Neg

+ = DC Pos and Fan +

F = Fan Neg

A = Light and Thermostat Power

C = Light and Tnhermostat Power

D = Blank

C = Thermostat contact

P = Blank

T = Thermostat contact

